

Fig. 1




Fig. 2




Fig. 3




Fig. 4




Fig. 5A





Fig. 5B

Fig. 6

66c



66d

42a

42b

42c

42d

networkcar

Mapping

Diagnostics

Service Records

Text Messaging

Status: Your vehicle is parked.

Vehicle Location as of 11/08/02 03:24 PM
Approximate Location: 7770 NORCANYON WAY
SAN DIEGO, CA 92126 US

154

Nearest Cross Street: 27.03 W NORCANYON WAY & LANDBREEZE WAY
Latitude / Longitude: 32.93369 / -117.15584

Ignition: Off

Vehicle is parked.

Maptui

158

Zoom Out
Country
Region
City
Street
Zoom In
Undo
Redo

Double Click: Zoom in Shift+Double Click: Zoom out Click Drag: Zoom to Selected Area more tips...
(C)2002 MapTui, NavTech.

Fig. 7

66e

Diagnostics		Mapping		Service Records		Text Messaging																																								
<p>Found 12 service record(s). Click the Invoice Date or Work Order #.</p> <table border="1"> <thead> <tr> <th>Invoice Date</th> <th>Work Order #</th> <th>Company</th> </tr> </thead> <tbody> <tr><td>11/10/03</td><td>209729</td><td>Honda of El Cerrito Service</td></tr> <tr><td>08/22/03</td><td>202481</td><td>Honda of El Cerrito Service</td></tr> <tr><td>08/21/03</td><td>199734</td><td>Honda of El Cerrito Service</td></tr> <tr><td>03/15/03</td><td>189065</td><td>Honda of El Cerrito Service</td></tr> <tr><td>02/03/03</td><td>185346</td><td>Honda of El Cerrito Service</td></tr> <tr><td>11/06/02</td><td>177232</td><td>Honda of El Cerrito Service</td></tr> <tr><td>09/06/02</td><td>171184</td><td>Honda of El Cerrito Service</td></tr> <tr><td>07/09/02</td><td>165170</td><td>Honda of El Cerrito Service</td></tr> <tr><td>06/17/02</td><td>161760</td><td>Honda of El Cerrito Service</td></tr> <tr><td>04/30/02</td><td>158293</td><td>Honda of El Cerrito Service</td></tr> <tr><td>03/28/02</td><td>155340</td><td>Honda of El Cerrito Service</td></tr> <tr><td>03/22/02</td><td>154370</td><td>Honda of El Cerrito Service</td></tr> </tbody> </table>								Invoice Date	Work Order #	Company	11/10/03	209729	Honda of El Cerrito Service	08/22/03	202481	Honda of El Cerrito Service	08/21/03	199734	Honda of El Cerrito Service	03/15/03	189065	Honda of El Cerrito Service	02/03/03	185346	Honda of El Cerrito Service	11/06/02	177232	Honda of El Cerrito Service	09/06/02	171184	Honda of El Cerrito Service	07/09/02	165170	Honda of El Cerrito Service	06/17/02	161760	Honda of El Cerrito Service	04/30/02	158293	Honda of El Cerrito Service	03/28/02	155340	Honda of El Cerrito Service	03/22/02	154370	Honda of El Cerrito Service
Invoice Date	Work Order #	Company																																												
11/10/03	209729	Honda of El Cerrito Service																																												
08/22/03	202481	Honda of El Cerrito Service																																												
08/21/03	199734	Honda of El Cerrito Service																																												
03/15/03	189065	Honda of El Cerrito Service																																												
02/03/03	185346	Honda of El Cerrito Service																																												
11/06/02	177232	Honda of El Cerrito Service																																												
09/06/02	171184	Honda of El Cerrito Service																																												
07/09/02	165170	Honda of El Cerrito Service																																												
06/17/02	161760	Honda of El Cerrito Service																																												
04/30/02	158293	Honda of El Cerrito Service																																												
03/28/02	155340	Honda of El Cerrito Service																																												
03/22/02	154370	Honda of El Cerrito Service																																												
<p>164</p> <p>168</p>																																														
<p>Service Record</p> <table border="1"> <thead> <tr> <th>Job Pay Type</th> <th>Operation</th> <th>Technician ID</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>Customer 01HOZ-37500 - 37500 MILE SERVICE</td> <td>33</td> </tr> <tr> <td></td> <td>Comments: CUSTOMER REQUESTS 37,500 MILE SERVICE ESTIMATE INCLUDES HAZARDOUS WASTE CHARGE; RECOMMENDED MAINTENANCE PERFORMED 37,500 MILE SERVICE</td> <td></td> </tr> <tr> <td>2</td> <td>Customer 30HOZ-FR2PDRTR - FRONT PAD/ROTOR</td> <td>33</td> </tr> <tr> <td></td> <td>Comments: NEEDS FRONT BRAKES; DUE TO NORMAL WEAR, REPLACED FRONT BRAKE PADS AND RESURFACED BOTH FRONT ROTORS</td> <td></td> </tr> </tbody> </table>								Job Pay Type	Operation	Technician ID	1	Customer 01HOZ-37500 - 37500 MILE SERVICE	33		Comments: CUSTOMER REQUESTS 37,500 MILE SERVICE ESTIMATE INCLUDES HAZARDOUS WASTE CHARGE; RECOMMENDED MAINTENANCE PERFORMED 37,500 MILE SERVICE		2	Customer 30HOZ-FR2PDRTR - FRONT PAD/ROTOR	33		Comments: NEEDS FRONT BRAKES; DUE TO NORMAL WEAR, REPLACED FRONT BRAKE PADS AND RESURFACED BOTH FRONT ROTORS																									
Job Pay Type	Operation	Technician ID																																												
1	Customer 01HOZ-37500 - 37500 MILE SERVICE	33																																												
	Comments: CUSTOMER REQUESTS 37,500 MILE SERVICE ESTIMATE INCLUDES HAZARDOUS WASTE CHARGE; RECOMMENDED MAINTENANCE PERFORMED 37,500 MILE SERVICE																																													
2	Customer 30HOZ-FR2PDRTR - FRONT PAD/ROTOR	33																																												
	Comments: NEEDS FRONT BRAKES; DUE TO NORMAL WEAR, REPLACED FRONT BRAKE PADS AND RESURFACED BOTH FRONT ROTORS																																													

Fig. 8




Fig. 9




Fig. 10